

Procedure

At least one of the following faults is saved:

- CDBF
- CDC0


Troubleshooting:

- Clear fault memory
- Carry out a system test on the electromotive throttle actuator
- If fault reoccurs:
 - Check voltage supply to throttle valve actuator
 - Program DME control unit
 - Carry out a system test on the electromotive throttle actuator

If fault reoccurs:

- Replace DME control unit.

Wiring diagram



Back

Next