The Little Speed Shop LLC 1770 Emerson St. Rochester, NY. 14606 (585) 647-0339

thelittlespeedshop@gmail.com www.thelittlespeedshop.com BAR# 7118662

Writer: SHAWNA TEMPLE

CUSTOMER: PETER MONTEFERRANTE YEAR: 2002 TRANS/DRIVE:

MAKE/MODEL: BMW M3 COUPE COUPE 2-DR LICENSE: GUH1824 VIN: WBSBL93422JR12914 MILES IN/MILES 104967/

Cell: (716) 491	-2421	VIN: ENGINE:	WBSBL93422JR12914 3.2L L6 DOHC 24V		S IN/MILES	104967/
In: 7/19/2019 Ou	ut: 7/19/2019 INSPECTION DUE F	PRODUCTION DATE TI	RE SIZE FRONT AND REAR	BODY STYLE	Email:	
VEHICLE ISSU	E #1: CHECK OVER					
TECH REPORT	T: PERF CHECKOVER					
LABOR:	DIAGNOSTIC LABOR				\$0.00	0 LABOR
				Tota	al for "CHECK	OVER": \$0.00
VEHICLE ISSU	E #2: NO OIL CAP - QUOTE REPLA	CEMENT OIL CAP				
TECH REPORT	Γ: REPLACED OIL FILLER CAP					
PART	OIL FILLER CAP			1 @ \$17.62	\$17.62	2 NEW
			Total for "NO OIL CAP -	QUOTE REPLA	CEMENT OIL	CAP": \$17.62
VEHICLE ISSU	E #3: REPLACEMENT OF BOTH RE	EAR WHEEL BEARINGS				
TECH REPORT	T: UPON REPLACEMENT OF WHEE CE. MUST BE REPLACED. REPLAC	EL BEARINGS FOUND C ED BOTH REAR WHEE	NE REAR HUB SCORED, WO BEARINGS AND LR HUB	ORN, AND PITTE	ED ON BEARII	NG INNER
PART	WHEEL BEARING			2 @ \$114.35	\$228.70	0 NEW
PART	WHEEL HUB W/O BEARING			1 @ \$134.87	\$134.8	7 NEW
LABOR:	LABOR TO REPLACE HUBS	IN CONJUNCTION WIT	H OTHER REPAIRS		\$420.00	0 LABOR
LABOR:	HUB, R&R				\$105.00	0 LABOR
			Total for "REPLACEMENT OF	BOTH REAR W	HEEL BEARIN	IGS": \$888.57
VEHICLE ISSU	E #4: REPLACEMENT OF BOTH RE	EAR LOWER BALL JOIN	TS AND ECCENTRIC BOLTS			
TECH REPORT	Γ: REPLACED LOWER BALL JOINTS	S AND BOLTS				
PART	CONTROL ARM BUSHING			3 @ \$77.02	\$231.0	6 NEW
PART	TRAILING ARM BOLT			2 @ \$9.67	\$19.34	4 NEW
PART	CONTROL ARM WASHER			2 @ \$6.16	\$12.32	2 NEW
PART	NUT			2 @ \$1.81	\$3.62	2 NEW
LABOR:	LABOR TO REPLACE REAR OTHER REPAIRS.	BALL JOINTS IN CONJ	JNCTION WITH		\$420.00	0 LABOR
	Total	for "REPLACEMENT OF	BOTH REAR LOWER BALL	OINTS AND EC	CENTRIC BOI	LTS": \$686.34
	E #5: QUOTE REAR SUBFRAME M ASSENGER SIDE FORWARD MOS		PLACEMENT SUBFRAME BUS	SHINGS, ETC	BEGINNING T	O SHOW
	T: REMOVED SUBFRAME AND WEI ND INNER UPPER ARM BUSHINGS					EAR
PART	E46 M3 COMPLETE SUBFRA	AME REINFORCEMENT	PACKAGE	1 @ \$265.00	\$265.00	0 NEW
Docommondos	l Donoiro:			Labor/Joh		¢c 711 00

Recommended Repairs:	Labor/Jobs	\$6,711.00
	Parts	\$4,066.36
	Sublet	\$0.00
	Total Fees	\$10.00
	Subtotal	\$10,787.36
	Tax @ 8%	\$862.99
	Total	\$11,650.35
	Payments	\$3,000.00
	Balance	\$8,650.35

Χ	Date 8/26/2019

The Little Speed Shop LLC 1770 Emerson St. Rochester, NY. 14606 (585) 647-0339

thelittlespeedshop@gmail.com www.thelittlespeedshop.com BAR# 7118662

GUH1824

Writer: SHAWNA TEMPLE

CUSTOMER: PETER MONTEFERRANTE

YEAR: 2002 TRANS/DRIVE: MAKE/MODEL: BMW M3 COUPE COUPE 2-DR LICENSE:

Cell: (716) 491-242	VIN: ENGINE:	WBSBL93422JR12914 3.2L L6 DOHC 24V	MIL	LES IN/OUT: 1	04967
PART	REAR SUBFRAME BUSHING SET, POLY 95A (BMW E46	i, Z4)	1 @ \$295.00	0 \$295.00	NEW
PART	RACE POLYURETHANE REAR TRAILING ARM BUSHING	G SET - E36, E46	1 @ \$89.98	8 \$89.98	NEW
PART	BMW E36 & E46 3 SERIES, Z4, X3 REAR UPPER ARM I	NER BUSHING	1 @ \$79.99	9 \$79.99	NEW
PART	BMW E36 & E46 REAR LOWER CONTROL ARM WITH B ADJUSTABLE	USHINGS	1 @ \$215.00	0 \$215.00	NEW
PART	BMW E46 M3 FRONT CONTROL ARM BUSHING- ALLOY	′	1 @ \$211.00	0 \$211.00	NEW
PART	TRAILING ARM BOLT		2 @ \$9.6	7 \$19.34	NEW
PART	NUT		2 @ \$4.8	1 \$9.62	NEW
PART	CONTROL ARM WASHER		2 @ \$6.10	6 \$12.32	NEW
LABOR:	LABOR TO REPLACE FRONT AND REAR SUBFRAME A BUSHINGS AND WELD IN FRONT AND REAR CHASSIS REINFORCEMENT. IF DONE IN CONJUNCTION WITH F DEPENDING ON THE EXTENT OF THE DAMAGE TO TH ADDITIONAL TIME FOR WELDING MAY BE REQUIRED.	AND SUBFRAME ROD BEARINGS . E FRAME		\$2,625.00	LABOR
LABOR:	ALIGNMENT - 4 WHEEL			\$140.00	LABOR
Total for "QUOT	Total for "QUOTE REAR SUBFRAME MOUNTING REPAIR, REPLACEMENT SUBFRAME BUSHINGS, ETC BEGINNING TO SHOW CRACKS ON PASSENGER SIDE FORWARD MOST MOUNTING POINT.": \$3,962.25				
VEHICLE ISSUE #	6: REAR TRAILING ARM BUSHING REPLACEMENT - POWI	ERFLEX BLACK			
TECH REPORT: R	EPLACED REAR TRAILING ARM BUSHINGS				
	Total for "REAR TRAI	ING ARM BUSHING RE	PLACEMENT -	POWERFLEX BI	_ACK": \$0.00
VEHICLE ISSUE #	7: QUOTE POWER STEERING LINES FROM PUMP TO RAC	CK			
TECH REPORT: R	EPLACED POWER STEERING LINES AND REPLACED FLU	ID			
PART	P/S PRESSURE HOSE		1 @ \$292.10	6 \$292.16	NEW
PART	AUTO TRANS FLUID D6 ATF - 1-LITER		1 @ \$22.9	1 \$22.91	NEW
LABOR:	P/S PRESSURE HOSE, R&R			\$189.00	LABOR
	Total for "C	QUOTE POWER STEERI	NG LINES FRO	OM PUMP TO RA	CK": \$504.07
VEHICLE ISSUE #	8: BELT TENSIONER				
TECH REPORT: R	EPLACED BELT TENSIONER				
PART	DRIVE BELT		1 @ \$35.70	6 \$35.76	NEW
PART	ACC. BELT TENSIONER ASSY W/ PULLEY		1 @ \$301.50	0 \$301.50	NEW
LABOR:	BELT TENSIONER, R&R			\$189.00	LABOR

Recommended Repairs:	Labor/Jobs	\$6,711.00
	Parts	\$4,066.36
	Sublet	\$0.00
	Total Fees	\$10.00
	Subtotal	\$10,787.36
	Tax @ 8%	\$862.99
	Total	\$11,650.35
	Payments	\$3,000.00
	Balance	\$8,650.35

Х	<i>,</i>	Date 8/26/2019

The Little Speed Shop LLC 1770 Emerson St. Rochester, NY. 14606 (585) 647-0339

thelittlespeedshop@gmail.com www.thelittlespeedshop.com BAR# 7118662

Writer: SHAWNA TEMPLE

CUSTOMER: PETER MONTEFERRANTE YEAR: 2002

MAKE/MODEL:

BMW M3 COUPE COUPE 2-DR WBSBL93422JR12914

TRANS/DRIVE: LICENSE:

GUH1824 MILES IN/OUT: 104967

Cell: (716) 491-2421

VIN: **ENGINE**: 3.2L L6 DOHC 24V

		Total for "BE	LT TENSIONER	R": \$526.26
VEHICLE ISSU	E #9: AIR CONDITIONING BELT			
TECH REPORT	T: REPLACED AC BELT			
		Total for "AIR COI	NDITIONING BE	LT": \$0.00
	E #10: CUSTOMER STATES DRIVER SIDE HEADLIGHT IS OUT AND PASSENGER D IGNITOR AND BULB AND MODULES ETC. HE DOESN'T CAR IF IT IS FACTORY		D OUT. TOWN	E TOLD
Total fo	or "CUSTOMER STATES DRIVER SIDE HEADLIGHT IS OUT AND PASSENGER SID NEEDED IGNITOR AND BULB AND MODULES ETC. HE DOESN'T CAI	E IS GOING IN AND O R IF IT IS FACTORY O	UT. TOWNE TO R AFTERMARK	OLD HIM IT ET": \$0.00
VEHICLE ISSU	E #11: QUOTE ROD BEARING REPLACEMENT			
TECH REPORT	T: PERFORMED ROD BEARING SERVICE AND LOF.			
PART	PERFORMANCE COATED ROD BEARING KIT AND ARP ROD BOLTS (BMW S54)	1 @ \$609.99	\$609.99	NEW
PART	MOTOR OIL 10W-60 RACETEC 1 LITER	6 @ \$15.64	\$93.84	NEW
PART	OIL FILTER KIT W/ O-RING	1 @ \$25.48	\$25.48	NEW
PART	OIL PAN GASKET METAL/RUBBER	1 @ \$47.24	\$47.24	NEW
LABOR:	CONNECTING ROD BEARING, R&R		\$3,024.00	LABOR
LABOR:	ENGINE OIL AND FILTER SERVICE		\$84.00	LABOR
	Total for "QUO	OTE ROD BEARING RE	EPLACEMENT"	\$3,884.55
VEHICLE ISSU	E #12: TECHNICIAN RECOMMENDS DRIVER SIDE LOW BEAM BULB BALLAST AN	ID BOTH SIDES LOW I	BEAMS	
PART	DRIVER SIDE HEADLIGHT BALLAST	1 @ \$608.00	(30% Discount) \$425.60	NEW
PART	HEADLIGHT LOW BEAM XENON BULB	2 @ \$113.00	\$226.00	NEW
LABOR:	LABOR TO REPLACE LOW BEAM BULBS AND BALLAST		\$52.50	LABOR
	Total for "TECHNICIAN RECOMMENDS DRIVER SIDE LOW BEAM BULB BAL	LAST AND BOTH SIDE	S LOW BEAMS	S": \$704.10
VEHICLE ISSU DIAG AND AD\	E #13: CUSTOMER STATES THAT WHEN DRIVING IN THIRD GEAR UNDER LIGHT /ISE	LOAD WHEN HE LIFT	TS POPS INTO	NEUTRAL
TECH REPORT	T: PERFORMED MANUAL TRANSMISSION FLUID FLUSH WITH BLACKSTONE SAM	IPLE IF NEEDED.		
PART	TRANSMISSION FLUID FLUSH	3 @ \$25.00	\$75.00	NEW
PART	BLACKSTONE OIL ANALYSIS	1 @ \$35.00	(25% Discount) \$35.00	NEW

Recommended Repairs:	Labor/Jobs	\$6,711.00
	Parts	\$4,066.36
	Sublet	\$0.00
	Total Fees	\$10.00
	Subtotal	\$10,787.36
	Tax @ 8%	\$862.99
	Total	\$11,650.35
	Payments	\$3,000.00
	Balance	\$8,650.35

Х	X	Date 8/26/2019

The Little Speed Shop LLC 1770 Emerson St. Rochester, NY. 14606 (585) 647-0339

thelittlespeedshop@gmail.com www.thelittlespeedshop.com BAR# 7118662

Writer: SHAWNA TEMPLE

CUSTOMER: PETER MONTEFERRANTE YEAR: 2002

MAKE/MODEL: BMW M3 COUPE COUPE 2-DR VIN: WBSBL93422JR12914

Cell: (716) 491-2421 ENGINE: 3.2L L6 DOHC 24V

TRANS/DRIVE: / LICENSE: GUH1824 MILES IN/OUT: 104967

Total for "CUSTOMER STATES THAT WHEN DRIVING IN THIRD GEAR UNDER LIGHT LOAD WHEN HE LIFTS POPS INTO NEUTRAL DIAG AND ADVISE": \$110.00 VEHICLE ISSUE #14: RECOMMEND OIL DRAIN PLUG TECH REPORT: WHILE PERFORMING WORK FOUND ALLEN HEAD OF OIL DRAIN PLUG STRIPPED - NEW ONE REQUIRED. REPLACED DRAIN **PLUG PART** OIL DRAIN PLUG \$2.21 NEW 1 @ \$2.21 Total for "RECOMMEND OIL DRAIN PLUG": \$2.21 VEHICLE ISSUE #15: RECOMMEND MOTOR MOUNTS TECH REPORT: FOUND MOTOR MOUNTS NEED REPLACEMENT. REPLACED MOTOR MOUNTS **PART ENGINE MOUNT** NEW 2 @ \$129.45 \$258.90 LABOR: REPLACE MOTOR MOUNTS, LABOR REDUCED TO OVERLAP \$52.50 **LABOR** Total for "RECOMMEND MOTOR MOUNTS": \$311.40

Total for RECOMMEND MOTOR MOUNTS . \$311.40

VEHICLE ISSUE #16: REAR WHEEL LUG NUT BROKEN, ADVISE ON WHEEL STUDS

PART RACE WHEEL STUD AND LUG PACKAGE 82MM 1 @ \$269.99 NEW LABOR: LABOR TO EXTRACT LUG BOLT AND INSTALL WHEEL STUDS \$210.00 LABOR

Total for "REAR WHEEL LUG NUT BROKEN, ADVISE ON WHEEL STUDS": \$479.99

PARTS DISCOUNT - \$500.00 LABOR DISCOUNT - \$800.00 YOUR TOTAL SAVINGS TODAY - \$1,300.00

Payment Rec'd American Express Date: 7/26/2019 \$3,000.00

Recommended Repairs:	Labor/Jobs	\$6,711.00
	Parts	\$4,066.36
	Sublet	\$0.00
	Total Fees	\$10.00
	Subtotal	\$10,787.36
	Tax @ 8%	\$862.99
	Total	\$11,650.35
	Payments	\$3,000.00
	Balance	\$8,650.35

X	Date 8/26/2019