



Congratulations on protecting your windshield with ClearPlex Invisible Windshield Protection Film®.

Remember, this film is not as hard as a windshield and is not permanent. There are several things you can do to improve the effectiveness and prolong the life of ClearPlex.

• CARING FOR CLEARPLEX •

- Remove any debris from the windshield wipers. Debris not removed prior to using the windshield wipers can scratch the film.
- Always use washer fluid when cleaning the windshield with wipers. Do not run the windshield wipers dry, as dry debris on the wipers can scratch the film.
- Do not use Rainex, or any other similar type of chemical water repellent on ClearPlex, as it can have the reverse effect on the ClearPlex film.
- Do not use any sort of acid wash on ClearPlex; it will ruin the film.
- Do not use sharp objects on the ClearPlex film. Windshield scrapers are fine, just make sure any type of scraper edge used on the ClearPlex film is not chipped or pitted. If your windshield scraper is damaged, chipped, pitted or rough, please replace your scraper.
- Clean ClearPlex regularly to remove staining items such as tree sap, bird droppings, tar, oils and bugs. Avoid using any cleaning solutions that contain petroleum distillates, alcohol, and silicone oils or like ingredients. Use a mild soap with water, and a soft cloth to clean.
- When cleaning your vehicle and/or windshield, do not point high-pressure water directly at the windshield. Do not put the exit of the high pressure water within 3 ft. of the windshield. Use soft brushes or clothes to clean the windshield, and use the water to softly rinse the film. This will prolong the life of the scratch resistant coating.

In the unlikely event that your windshield does crack or chip due to an impact, the crack or chip can often be repaired through the ClearPlex film. ClearPlex film typically does not need to be removed to repair the crack or chip. Make sure the repair-person knows ClearPlex is on the windshield, and to use caution when removing any excess repair material.

Drying and curing time is necessary for proper bonding of the Invisible Windshield Protection Film® to your windshield. To insure initial bonding, do not high-pressure wash the Invisible Windshield Protection Film® for a period of 72 hours after installation. No claim under this Limited Warranty will be valid if the Invisible Windshield Protection Film® is subjected to high-pressure wash equipment within 72 hours of installation.

If you wear polarized sunglasses, there is a possibility that under certain conditions (bright sunlight and the angle of the sun to your windshield), you may see a “corona” effect. This slight “corona” effect is visible as a prism, or rainbow of colors. If you find this minimal “corona” effect impairs your vision while driving, remove the ClearPlex film from your windshield immediately.

DO NOT OPERATE YOUR VEHICLE IF THE INVISIBLE WINDSHIELD PROTECTION FILM® YELLOWS, CRACKS, BUBBLES UP, PEELS OR OTHERWISE ADVERSELY IMPAIRS THE CLARITY OF THE WINDSHIELD. OPERATION OF YOUR VEHICLE UNDER SUCH CONDITIONS MAY CAUSE SERIOUS DAMAGE OR INJURY TO YOU, YOUR VEHICLE OR OTHER PERSONS. ClearPlex hereby disclaims liability for damage or injuries caused by operation of your vehicle under such conditions. The ClearPlex Invisible Windshield Protection Film® should be removed from the windshield immediately if any of the above mentioned physical conditions of the Invisible Windshield Protection Film® exist.

• HOW TO REMOVE CLEARPLEX •

- Using an object such as a knife or key, lift up one corner of the film. Using constant pressure – pull the film off the windshield.
- If you decide you would like to use a knife or blade to score the film, [cut the film with a stainless steel blade only](#). A stainless steel blade used with moderate pressure will not scratch the windshield. Other types of metal blades may scratch the windshield.
- Clean your windshield of any adhesive remaining on the glass using soap and water.

If you have any questions or concerns about care and maintenance, contact your local installer or ClearPlex Corporation at 801-571-8243.



P.O. Box 216
Draper, UT 84020
Tel: 801.571.8243
Fax: 801.905.8451

www.clearplex.com