

Wed Jan 06 17:21:10 EST 2010

Warranty Vehicle Inquiry

B584572 CONFIDENTIAL

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2010 BMW of North America, LLC

Vehicle Data	
VIN: WBSNB93516B584572	Davis #: N/A
Chassis Number: B584572	Assist Safety Plan Expires: 05/04/2009
Line Make: 01 - BMW	Assist Conv. Plan Expires: 00/00/0000
Model Year: 2006	TCU ESN / TCU IMEI: 10215200677 ACTIVE
AG Model Code/Desc: NB93 - M5	TCU MIN: XXX-XXX-XXXX
NA Model Code/Desc: 0651 - M5	MDN / MSISDN: XXX-XXX-XXXX
Interior Trim Code: X2A9 - Silverstone Perf Full Leather.	Vehicle Production Date: 2006/03
Exterior Color Code: A29 - Silverstone Metallic	Motor Type: S85
MSRP: \$94,650.00	Platform/Engineering Series: E60
	Wholesale Center ID/Loc: 46891-01
	Wholesale Date: 05/03/2006
	Retail Center ID/Loc: 46891-01
	Retail Date: 05/04/2006
	In-Service Date: 05/04/2006

New Vehicle Warranty Info

No Coverage As Of: 05/04/2010

Expiration Mileage: 50,000

NO OPEN CAMPAIGNS

Option Information	
Code	Description

Chassis Number : B584572

0ZFA	First aid kit	0ZFM	Floor mats
01CA	CO2 relevant vehicles	0261	Rear side-impact airbags
0319	Universal garage-door opener	0322	Comfort Access keyless entry
04MA	Multi-function seats w/lumbar	04MF	Active seat width adjustment
0403	Moonroof	0415	Power rear sunshade
0416	Rear sunshades	0430	Auto-dimming mirrors
0431	Auto-dimming rearview mirror	0441	Smoker's package
0453	Front ventilated seats	0502	Retractable headlight washers
0508	Park Distance Control	0524	Adaptive light control
0609	Navigation system	0610	Head-up Display
0620	Voice-command	0639	BMW Assist w/Bluetooth System
0655	Satellite radio w/1 year sub.	0672	6-disc CD changer
0677	Logic7 sound system	0697	DVD Area coding, North America
0737	Aluminum interior trim	0754	Rear spoiler
08SP	CO2 control	0818	Battery switch
09AA	Transport protection	0925	Shipping package

Customer Information

Name (First/Last): DR. STEVEN GOFF
Address: 8962 ESTATE DR
WEST PALM BEACH FL 33411-6595 UNITED STATES

Contract/Service Program Information

Type	Program Code/Desc	Contract Number/Status	Eff Date	Enroll Date	No Coverage As Of	Exp Age (Mth)	Exp Odometer (Miles)	Retail Center	Center Name	Vendor Code Used	Contract Holder (First/Last)
MP	0000000168 - MP 48 MO/050K MLS	10000000 ACTIVE	05/04/2006	05/04/2006	05/04/2010	48	50,000	46891	Braman Motorcars	MP	

ELIGIBLE Contract/Service Program Information (Optional programs only, CPO eligibility not provided)

Type	Program Code/Desc	Wholesale Price	MSRP	Deductible	Vendor Code Used
MP	0000000184 - MP 72 MO/100K MLS	N/A	3495.00	.00	MP
ESC	0000000015 - ESC PT+ 60M/100K Mls	N/A	2840.00	50.00	PT
ESC	0000000018 - ESC GD 60M/100K Mls	N/A	4230.00	50.00	GD

Chassis Number : B584572

ESC	0000000021 - ESC PL 60M/100K MIs	N/A	4740.00	50.00	PL
ESC	0000000024 - ESC PT+ 72M/100K MIs	N/A	3360.00	50.00	PT
ESC	0000000027 - ESC GD 72M/100K MIs	N/A	5100.00	50.00	GD
ESC	0000000030 - ESC PL 72M/100K MIs	N/A	5740.00	50.00	PL
ESC	0000000033 - ESC PT+ 84M/70K MIs	N/A	3420.00	50.00	PT
ESC	0000000036 - ESC GD 84M/70K MIs	N/A	5200.00	50.00	GD
ESC	0000000039 - ESC PL 84M/70K MIs	N/A	5870.00	50.00	PL
ESC	0000000042 - ESC PT+ 84M/100K MIs	N/A	4110.00	50.00	PT
ESC	0000000045 - ESC GD 84M/100K MIs	N/A	6350.00	50.00	GD
ESC	0000000048 - ESC PL 84M/100K MIs	N/A	7180.00	50.00	PL

Disclaimer: The Eligible Contract indicators do not necessarily mean that the vehicle/vehicle owner is currently eligible for the indicated contracts. The Eligible Contract indicators are only suggestions to the dealer, based on the latest data to which BMW has access about the vehicle. For actual enrollment of the vehicle in any of the optional programs, please use the Vehicle Contract System.

Repair History (Claims)

Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description
46891	01	258260	07/20/2009	599616	07/16/2009	07/20/2009	N/A	35,573	1112194800 2300566600 6610151200 85990101MP 85990501MP 85990601MP	Cylinder head cover, spark plug well leaking SMG forward power transmission no effect Key battery, remote control permanent failure VEHICLE CHECK STANDARD OPERATION MP SPARK PLUG REPLACEMENT (CBS VEHICLE)
46891	01	90510	11/07/2008	569246	11/03/2008	11/07/2008	N/A	26,171	11009999SA 1231081500	BMW NA RENTAL COST - GOODWILL Voltage regulator permanent malfunction
46891	01	81270	10/28/2008	566714	10/21/2008	10/28/2008	N/A	25,826	1136034800 11720376MP 3241074800 61610077MP 85990091MP 85990501MP	Oil line for camshaft adjusting unit leaking ENG AIR FILTER-DIRTY-MP Suction line from oil tank to pump leaking FT WIPER RUBBER INSERT-MP OIL SERVICE(MP)AFTER THE 1ST STANDARD OPERATION MP
46891	01	24120	07/28/2008	554417	07/24/2008	07/28/2008	N/A	23,829	5116004100 64310237MP 85990501MP	Exterior mirror cover poorly adapted/fitted MICROFILTER REPLACEMENT STANDARD OPERATION MP

Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code Description
46891	01	576190	03/24/2008	535289	03/19/2008	03/24/2008	N/A	19,910	3400077MP BRAKE FLUID CHANGE- FULL MAINTENANCE PROGRAM 85990501MP STANDARD OPERATION MP
46891	01	452730	09/14/2007	505852	09/13/2007	09/14/2007	N/A	13,633	0012300200 SIB #12-18-06 RECALL 06E-A04 DME REPROGRAMMING ON M5/M6 S85 FROM START OF PRODUCTION TO 08/30/2006
46891	01	452720	09/14/2007	505852	09/13/2007	09/14/2007	N/A	13,633	5116331300 Drink holder, front broken 61610077MP FT WIPER RUBBER INSERT-MP 85990091MP OIL SERVICE(MP)AFTER THE 1ST 85990501MP STANDARD OPERATION MP
46891	01	248000	09/20/2006	452780	09/18/2006	09/20/2006	N/A	3,434	0061510200 SIB #34-05-06 LBL 477 CHECK SZL OPTICAL ELEMENT ON E60/61/63/64 PROD FROM 8/26/05 TO 7/28/06
46891	01	194770	06/22/2006	440026	06/16/2006	06/22/2006	N/A	1,318	85990088MP 1200 MI SERV -M5,Z8,S54B32 M3 85990501MP STANDARD OPERATION MP
10712	01	817940	05/09/2006	80761	04/17/2006	05/09/2006	N/A	2	0033570100 VDC only. Take no action.

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.
© 2010 BMW of North America, LLC