

Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description
46891	01	169230	03/03/2009	584793	03/02/2009	03/03/2009	0	1,353	85990088MP	1200 MI SERV -M5,Z8,S54B32 M3
									85990501MP	STANDARD OPERATION MP
46891	01	106360	11/28/2008	573188	11/26/2008	11/28/2008	0	1	11999977BV	QCI SPOT DELIVERY

----- End of Print -----

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2018 BMW of North America, LLC

Warranty Vehicle Inquiry

Sat Oct 06, 2018 10:14:57 EDT

VIN(Last Seven) : PY43764 CONFIDENTIAL

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2018 BMW of North America, LLC

Vehicle Data

VIN: WBSWD93559PY43764

Chassis Number: PY43764

Line Make: 01 - BMW Car

Model Year: 2009

AG Model Code/Desc: WD93 - M3 Coupe

NA Model Code/Desc: 0937 - M3 Coupe

Motor Type: S65

Exterior Trim Code: A73 - Jerez Black Metallic

Interior Color Code: NCH3 - Bamboo Beige Novillo Leather

MSRP: \$72,770.00

Davis #: 14

Assist Safety Plan Expires: 01/10/2013

Assist Conv. Plan Expires: 00/00/0000

TCU ESN / TCU IMEI: 351534015307153 INACTIVE

TCU MIN: XXX-XXX-XXXX

MDN / MSISDN: XXX-XXX-XXXX

Vehicle Production Date: 2008/10

Series: E92

Wholesale Center ID/Loc: 46891-01

Wholesale Date: 11/25/2008

Retail Center ID/Loc: 46891-01

Retail Date: 01/10/2009

In-Service Date: 01/10/2009

Campaign Details as of: October 6, 2018 at 10:14:55 AM EDT

Open Campaign Information

Stop Sale	Stop Code	Defect Code	Defect Description	Bulletin Number	Recall Number	Remedy Status	Campaign Status	Reserved By, Reserved Date
		0061660400	B640717 Recall: Blower Motor Wiring	B64 07 17	17V-676		00-Open	

Option Information

Code	Description	Code	Description
------	-------------	------	-------------

0ZPP	Premium Package	0ZTP	Technology Package
01CA	CO2 relevant vehicles	02MK	M Double-clutch Transmission
02MT	19" Alloy Double-spoke wheels	02VB	Tire pressure monitor
0441	Smoker's package	0490	Adjustable seat width
04AE	Adjustable front armrest	04MY	Carbon Leather interior trim
0507	Park Distance Control (rear)	0521	Rain sensor and auto headlight
0563	Ambient Lighting	05GA	Alarm pre-wiring
0615	Online Information Services	0655	SiriusXM Radio w/ 1 year sub.
0697	DVD Area coding, North America	06AA	BMW TeleServices
06AB	TeleService Control	06FL	iPod and USB adapter
0752	Enhanced Premium Sound	0760	Shadowline exterior trim
08S4	Variable Light Decoding	08SC	TeleService Activation
08SP	CO2 control	0925	Shipping package

Customer Information

Name (First/Last): MR. EMMANUEL GERENA
 Address: 4431 YACHTMANS CT
 ORLANDO FL 32812-8081 UNITED STATES

Warranty/Maintenance Programs/Contract Services(Administered by BMW NA)

Type	Warr/Program Codes/Desc	Contract Number/Status	Eff Date	Enroll Date	No Coverage As Of	Exp Age (Mth)	Exp Odometer (Miles)	Current Age (Mth)	Retail Center	Center Name	Vendor Code Used	Contract Holder (First/Last)
	New Vehicle Limited Warranty	0000000 EXPIRED	01/10/2009		01/10/2013	48	50,000	117				
MP	0000000168 - MP 48 MO/050K MLS	0000000 EXPIRED	01/10/2009	01/10/2009	01/10/2013	48	50,000	117	46891	Braman Motorcars	MP	
FE	Federal Emissions 8/80 FE 96 MO/80K MLS	0000000 EXPIRED	01/10/2009	01/10/2009	01/10/2017	96	80000	117	46891	Braman Motorcars	00	
CA	California Emissions	Vehicle may qualify for California Emissions Coverage. Please verify if the vehicle was sold or is registered in a California Emissions Covered State (AZ,CA,CT,DE,MA,MD,ME,NJ,NM,NY,OR,PA,RI,VT,WA). Please confirm model year, selling state and current registration of the vehicle and click here to determine coverage.										

Repair History (Claims)

Center ID	Location ID	Claim Number	Claim Date	Repair Order #	Repair Order Date	Repair Entry Date	Davis #	Mileage	Defect Code	Description
14000	01	725980	09/02/2016	257369	09/02/2016	09/02/2016	1	50,204	0032350200	B650416 Recall: Driver's Front Air Bag
46891	01	86489	11/16/2015	865076	11/03/2015	11/16/2015	0	39,568	99999977PL	PLATINUM PROGRAM COVERAGE \$50 PER REPAIR VISIT
46891	01	86480	11/16/2015	865076	11/03/2015	11/16/2015	0	39,568	64510048PL	Air conditioning evaporator, front Leaking
46891	01	555599	07/02/2014	802743	06/28/2014	07/02/2014	0	36,990	99999977PL	PLATINUM PROGRAM COVERAGE \$50 PER REPAIR VISIT
46891	01	555590	07/02/2014	802743	06/28/2014	07/02/2014	0	36,990	11280139PL	Belt tensioner Unpleasant noises
46891	01	76210	11/08/2012	734562	11/06/2012	11/08/2012	2	28,103	67630312PL	PUMP, WINDSHIELD CLEANING SYSTEM PERMANENT FAILURE
46697	01	4820	06/22/2012	483160	06/21/2012	06/22/2012	0	25,415	5113194100	Roof trim strip poorly adapted/fitted
									6137117900	USB port, centre console incorrect connection /contact
									61610077MP	FT WIPER RUBBER INSERT-MP
									85990091MP	OIL SERVICE(MP)AFTER THE 1ST
									85990101MP	VEHICLE CHECK
									85990501MP	STANDARD OPERATION MP
46697	01	846000	01/17/2012	458307	01/10/2012	01/17/2012	7	22,199	34000077MP	BRAKE FLUID CHANGE- FULL MAINTENANCE PROGRAM
46697	01	477360	01/11/2011	402068	01/07/2011	01/11/2011	4	15,125	64310237MP	MICROFILTER REPLACEMENT
46697	01	477350	01/11/2011	402068	01/07/2011	01/11/2011	4	15,125	85990087MP	MP-LOW MILEAGE ANNUAL OIL SERVICE
									85990501MP	STANDARD OPERATION MP
									6610151200	Key battery, remote control permanent failure
									0028010100	E8x E9x US Programming control units (DKG control unit)
									11720376MP	ENG AIR FILTER-DIRTY-MP
									5113194100	Roof trim strip poorly adapted/fitted
									6121001200	Vehicle battery permanent failure
									6577011200	Front airbag sensor (acceleration sensor) Permanently failed
									85990091MP	OIL SERVICE(MP)AFTER THE 1ST
									85990501MP	STANDARD OPERATION MP
46697	01	368370	09/28/2010	386028	09/26/2010	09/28/2010	0	12,941	34000077MP	BRAKE FLUID CHANGE- FULL MAINTENANCE PROGRAM
									61610077MP	FT WIPER RUBBER INSERT-MP
									64310237MP	MICROFILTER REPLACEMENT
									85990501MP	STANDARD OPERATION MP

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.
© 2018 BMW of North America, LLC